


**NOTICE****U.S. DEPARTMENT OF TRANSPORTATION  
FEDERAL AVIATION ADMINISTRATION****N 3900.58****SEP 19 2002**Cancellation  
Date:**SUBJ: SAFETY HAZARD**

1. **PURPOSE.** Tektronix has initiated a recall for two oscilloscope models, TDS-210 and TDS-220. The reason, a design defect can cause personal injury or death.
2. **DISTRIBUTION.** This Notice is distributed to all Airway Facilities field offices with a standard distribution.
3. **ACTION.** If any FAA facility has a Tektronix TDS-210 or a TDS-220 oscilloscope with a serial number listed below, immediately verify whether the product has or has not been modified. Unless the equipment with the below serial numbers are marked with a white, vertically oriented Tektronix decal marked "P.S. MOD SUP 40-003", it means the oscilloscope has not been modified and shall be removed from service immediately. Contact Tektronix Recall Center at 1-800-835-9433 for instructions.

Model #	TDS 210	TDS 220
Serial	B010100 to B049399	B010100 to B041059
Numbers	BU10000 to BU50199 C010000 to C010879	BU10000 to BU50199 C010000 to C011174

4. **BREVITY.** Majority of the above listed oscilloscopes are coming into FAA possession via: legal statute takeover of air navigation facilities; during transition from a non-Fed property into the FAA possession; Congressionally mandated take over of the air navigation facility or other unspecified reasons. Immediate action shall be taken by all field managers to review their property records for these defective oscilloscopes. Remove any non-modified Tektronix TDS-210 or TDS-220 from the operational environment until the modification has been installed. Contact your local Regional Test Equipment Program Managers in AXX-470 for any additional information.

  
Steven B. Zaidman  
Director of Airway Facilities

